



# ADDITION TO THE PPE EXAMINATION PROCEDURE FOR ABSORBICA lanyards L57, L70150 I, L70150 Y, L70150 IM, L70150 YM

MAY 2011



1 - Open the zipped protective pouch which contains the tear webbing part of the absorber.



2 - Carefully remove the white tear webbing part from the pouch.



3 - At the lanyard end, check on each side of the webbing that there are **4** black bar tacks connecting the tear webbing to the attachment loop or steel ring.



**OK!**

4 - At the harness end, check on each side of the webbing that there are **4** black bar tacks connecting the tear webbing to the attachment loop.

**OK!**



**If any of the bar tacks do not meet the above requirements**  
*(complete or partial absence of one or more bar tacks, distorted, damaged or cut threads)*  
**then the item must be removed from service and forwarded to your Petzl distributor.**

**5 - Continue with the complete PPE examination procedure for the item.**

(instructions can be found on <http://www.petzl.com/fr/inspection-epi>).

Record the results of each PPE Examination.

In case of any doubt, contact your Petzl distributor.

**Forward all information to**  
**[inspection.absorbica@petzl.fr](mailto:inspection.absorbica@petzl.fr)**  
**Client – country – number of items examined**

For each examination performed record; the client name and contact details, date of examination, Petzl product reference, individual serial number, results of the inspection and the name of the inspector who performed the examination.



## ADDITION TO THE PPE EXAMINATION PROCEDURE FOR ABSORBICA lanyards L58, L58 MGO, L59, L59 MGO

MAY 2011



1 - Open the zipped protective pouch which contains the tear webbing part of the absorber.



2 - Carefully remove the white tear webbing part from the pouch.



3 - At the lanyard end, check on each side of the webbing that there are **5** white bar tacks connecting the tear webbing to the black lanyard components.



**OK!**

4 - At the harness end, check on each side of the webbing that there are **4** black bar tacks connecting the tear webbing to the black attachment loop.

**OK!**



**If any of the bar tacks do not meet the above requirements**  
*(complete or partial absence of one or more bar tacks, distorted, damaged or cut threads)*  
**then the item must be removed from service and forwarded to your Petzl distributor.**

**5 - Continue with the complete PPE examination procedure for the item.**

(instructions can be found on <http://www.petzl.com/fr/inspection-epi>).

Record the results of each PPE Examination.

In case of any doubt, contact your Petzl distributor.

**Forward all information to**  
**[inspection.absorbica@petzl.fr](mailto:inspection.absorbica@petzl.fr)**  
**Client – country – number of items examined**

For each examination performed record; the client name and contact details, date of examination, Petzl product reference, individual serial number, results of the inspection and the name of the inspector who performed the examination.